

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



TITLE: Electroporation-Mediated Intravascular Delivery
SN: 10/020,531
BLG: GTI-1180-CON1





FIG. 1




Title: Electroporation-Mediated Intravascular Delivery
SN: 10/020,531
BLG: GTI-1180-CON1

Before autofluorescence correction (2 hrs. after excision)



Pulsed
artery



FIG. 2A



Non-pulsed
artery

FIG. 2B

Before autofluorescence correction (2 hrs. after excision)




R1L1: Heparin, no pulse
(left artery) 8hrs.

FIG. 3A




R1R1: Heparin, with pulse
(right artery) 8hrs.

FIG. 3B



R2L1: Heparin, with pulse
(left artery) 5hrs.

FIG. 3C




R2R1: Heparin, no pulse
(right artery) 5hrs.

FIG. 3D




4L2: Heparin, with pulse (left artery)
FIG. 4A




4R2: Heparin, no pulse (right artery)
FIG. 4B



4L1: Heparin, with pulse (left artery)
FIG. 4C



1L3: Heparin, no pulse (left artery)
FIG. 4D



12R1: Heparin, with pulse (right artery)

FIG. 5A



12L1: Heparin, no pulse (left artery)

FIG. 5B




FIG. 6




FIG. 7





FIG. 8A




FIG. 8B




FIG. 8C